BH Series 180mm CHART DOT- PRINTING TYPE HYBRID RECORDER



MODEL BH □□□

The BH Series hybrid chart recorders are easy to operate and use the reliable dot-printing method to record a variety of information in analog and digital formats on a 180mm wide chart.

Not only can each measured value be read from the custom made analog scale plate but a comprehensive LED display also enables precise digital measurements to be taken by the user.

The compact BH Series instruments have depth of only 195mm which makes them suitable for space sensitive installations including panel mounting.

■FEATURES

• Ready to run immediately

As the recorders are pre-set to meet individual customer specifications and precise application requirements, the units start indicating and recording as soon as they are switched on.

• Dual displays for accuracy and simplicity

Measured values can be read at a glance, directly from maximum 6 multi scale analog display plate whilst a digital display clearly indicates measured values, alarm settings and chart speed together with a range of other information.

• Compact and easy to install

The BH recorders are designed for use in applications where space is at a premium. With a reduced depth of 195mm and weighing 7.0kg, the instruments are ideally suited for panel mounted installations.

· Abundant functions installed

An abundance of easy-to-use functions including skip function, digital recording, year/month! day printing and key lock are installed. A variety of options including high-speed-dotting, external drive and alarm output are prepared to meet every requirements.


• Input signal shift function

Shift correction of indications can be done every point according to the sensor input signals. The indication and recording scale positions can be corrected.

· Conforms to CE-marking




■ MODELS



^{*} For the combinations by channels, refer to the reference measuring range.

■ NAMES AND FUNCTIONS OF COMPONENT PARTS




CH.NO: Data display point No.
DATA: Measured value or time display



■ RECORDING FORMAT


• Fixed time digital printing

Time, scale, chart speed, setting change mark, and hour lines are printed on analog recording at optional time intervals together with data recording.




• Instantaneous digital recording

When the latest data are necessary, analog recording is interrupted at once to record these data.



• Printing of occurrence and reset of alarms

Time, point No., alarm type, and level are printed when an alarm occurred and the alarm was reset.



■ GENERAL SPECIFICATIONS

Input signals:

DC voltage $\dots \pm 7mV$, $\pm 14mV$, $\pm 25mV$,

±70mV, ±5V

DC current Applicable by adding a shunt

resistor (100Ω , 250Ω)

Thermocouple B, R, 5, K, E, J, T, N, Ni-NiMo,

AuFe-Cr, PR5-20, PR20-40,

WWRe5-26, WWRe0-26,

Platinel, U, L

Resistance thermometer

...... Pt100, JPt100, Pt-Co

Specify from the standard scale table every input point. (These input signals are combinable with each other in case of the thermocouple/DC voltage, or resistance thermometer/5V range only. See the reference setting range.)

Max. 6 multi scale plate is available.

Scale: Specify the scales within the minimum setting range.

Reference measuring range	Minimum measuring range
7.0mV range	More than 3.2mV span
14.0mV range	More than 6.3mV span
25.0mV range	More than 11 .3mV span
70.0mV range	More than 31.5mV span
5.0V range	More than 2.3V span
120Ωrange	More than 20.0 Ω span
140 Ω range	More than 20.0 Ω span
160Ωrange	More than 27.0 Ω span
220Ω range	More than 54.0 Ωspan
340 Ω range	More than 108.0 Ωspan

^{*}The reference voltage input is 0 mV (0V), while the reference resistance input is 100Ω .

Accuracy rating: Digital indications and printing

Thermocouple, resistance thermometer

..... \pm 0.3% of the scale range \pm 1 digit. When the scale range less 300°C, accuracy rating is \pm 1°C.

DC voltage \pm 0.1% of the reference measuring range \pm 1 digit

Analog indication..... \pm 0.5% of the scale range

*Note: Accuracy at a room temperature of $23^{\circ}\text{C} \pm 2^{\circ}\text{C}$

*Note: For thermocouple inputs, the reference junction compensating accuracy is excluded.

* Exceptional setting of accuracy rating

Input type	Scale	Accuracy rating (with reference to the reference measuring range)
WWRe0-26	0 to 100°C	±0.3% ± 1 digit
PR20-40 PR5-20	0 to 300°C 300 to 800°C 0 to 100°C	$\pm 1.5\% \pm 1$ digit $\pm 0.8\% \pm 1$ digit $\pm 4\%$
	100 to 200°C	± 0.5% ± 1 digit
AuFe-Cr	0 to 20K 20 to 50K	± 0.5% ± 1 digit ± 0.3% ± 1 digit
Pt-Co	4 to 20K 20 to 50K	\pm 0.5% \pm 1 digit \pm 0.3% \pm 1 digit

Reference junction compensating accuracy:

K, E, J, T, N, Platinel Lower than \pm 0.5°C

R, S, Ni-NiMo, AuFe-Cr, WWRe5-26,

WWRe0-26, U, LLower than ± 1.0°C

A/D resolution: About 1/18000 Allowable signal source resistance:

Thermocouple input, DC voltage input Lower than $1k\Omega$ (without burnout)

Resistance thermometer input

..... Lower than 10Ω per wire (Pt 100, JPt 100)

Input resistance:

Thermocouple input, DC voltage input About $8M\Omega$

*About 1M Ω when a voltage divider is used.

Common mode rejection ratio: More than 130dB

Series mode rejection ratiα More than 50dB

No. of measuring points: 6 points, 12 points,

24 points

Measuring cycle: 6 points about 5sec. 12 points

about 10sec, 24 points about

20sec

Temperature dri ft: $\pm 0.01\%$ of full scale/°C

(equivalent to E.M.F. for

thermocouple input)

Terminal board: Detachable type Removable for

connections

Dot-printing cycle: About 5 sec/point (when the

chart speed is faster than 6mm/h)

Recording system:

Analog recording Wire dot system 6-color

ribbon

Digital recording Wire dot system 6-color

ribbon

^{*}See the reference setting range.



Recording color:

Analog recording Red, black blue, green, brown,

Digital recording

Same colors as dot printing colors
Chart speed

Black Alarm occurrence & reset printing.....

Recording chart:

Fan-fold type 200mm total width, 20m total length,

180mm effective recording width

Chart speed:

12.5, 25, and 50mm/h (standard)

3-speed selection by DIP switches

*The speeds are optionally settable.

1 to 1500mm/h (1mm step)

12.5mmlh is a special example.

Fixed time digital recording:

Time, point No, measured values, and units are printed on analog recording at every specified time interval.

Chart speed(mm/h)	Fixed time digital printing interval
0 to 5	Not printed.
6 to 15	24 hours
16 to 25	12 hours
26 to 35	8 hours
36 to 45	6 hours
46 to 65	4 hours
66 to 85	3 hours
86 to 155	2 hours
156 to 250	1 hour
251 or more	Not printed.

Instantaneous digital recording:

Time, point No., measured values, and units are printed at the request time by interrupting analog recording.

Date and time printing:

Hour lines and time are printed on the hour sharp. Date (year, month, and day) is printed at zero hour sharp.

If this printing overlaps digital recording, time may be not printed.

*The printing intervals depend upon the chart speeds.

Chart speed (mm/h)	Time printing interval	Hour line printing interval
1	12 hours	6 hours
2	6 hours	3 hours
3	4 hours	2 hours
4	3 hours	2 hours
5 to 9	2 hours	1 hour
10 to 250	1 hour	1 hour
251 or more	Not printed.	Not printed.

Scale and point No. printing:

Point No. is printed at 6mm intervals beside the analog recording. Scales are printed sequentially every point at intervals of 48mm at 0% and 100% positions of the chart.

Chart speed printing:

The executing chart speed is printed on the 0 % side of the chart at intervals of 84mm as well as when the power supply is turned on.

*If digital printing is done halfway, the printing interval is extended at a high chart speed.

Alarm occurrence and reset printing:

Time, point No., alarm type and level are printed on the right side of the chart when an alarm occured.

Time, point No., and level are printed on the right side of the chart when the alarm was reset.

Setting change mark printing:

A character indicating a change item is printed on the 100% side of the chart at the end of a setting change (when communication interface option is added).

Skip function:

None of analog indications, dot-printing, digital display, and printing is done at each point.

*If the chart speed is lower than 35mm/h, the dot-printing interval may be delayed.

Analog indications: Scale plate and scale pointer Scale plate: Max. 6 multi scale, 150 equal divisions Status display:

Recording ON/OFF ... Green LED, illumination switch ALM Red LED flickers when an alarm occured.

PRT Green LED lights during printing.

Digital display:

7-segment LED, character height 15mm

2 digits... ... Point No.

5 digits... ... Data display -9999 to 99999

Display items:

Multi-point sequential display, 1-point cont inuous display, and clock display are switched.

Setting mode display (setting, check, operation):

Digital display part is shared by key operation. Data printing (instantaneous digital recording) operation, chart speed setting, time setting, alarm setting (when the alarm option is added) data interval setting, skip setting

Continuous indication operation:

Input entry and continuous indications at specified points only (recording stop)

Kinds of keys:

REC. ON, FEED, ENTRY, ♠, SEL

Recording operation:

REC. ON... ... Recording operation ON/OFF FEED Quick chart speed

Rated supply voltage:

90 to 120VAC, or 180 to 240VAC (to be specified)

Rated supply frequency:

50Hz/60Hz (selectable by DIP switches)

Maximum power consumption: Approx. 45VA

Working temperature range: 0 to 50°C

Working humidity range:

20 to 80%RH (No condensing is allowed.)

Mounting position:

Forward tilting 0° Backward tilting 0 to 30° Lateral tilting 0°

Warm-up time: Longer than 30mm

Countermeasure against power interrupt ion:

Setting data are kept unerased by EEPROM. Clock is backed up for longer than 10 years by a lithium battery (soldering)(assuming that the recorder is used for 8 hours a day).

Insulation resistance:

500VDC, higher than 20Mg between measuring terminals and protective conductor terminal 500VDC, higher than $20M\Omega$ between power terminals and protective conductor terminal 500VDC, higher than $20M\Omega$ between measuring terminals and power terminals

Dielectric strength:

500VAC, 1min between measuring terminals and protective conductor terminal

500VAC, 1min between power terminals and protective conductor terminal

500VAC, 1min between measuring terminals and power terminals

Casing:

perature Max. 80°C)

Power supply Steel plate

Color:

Door..... Black (equivalent to Munsell code N3.0)

Rear casing.....Gray (equivalent to Munsell code N7.0)

Mounting method: Panel flush-mount **Weight:** Approx. 7.0kg

• Transportation and storage conditions

Temperature: -20 to +60°C

Humidity: 5 to 95%RH (No condensing)

Vibrations: 10 to 60Hz 0.5G Shock: Less than 40G



This also offers the following maintenance functions.

However these functions are performed by IBM-PC at CHINO's agents, world wide.

ENG1 mode (Specifications check)
 Input parameters(ranges, scales, units)
 Alarm(mode, output destinations, AND/OR
 *when an alarm option is provided.)
 Recording colors
 Key lock(Key lock condition check by means)

of communication)
• ENG2 mode (Communication option setting and external drive option output specifications check)

Communication setting (addresses, baud rates, character configuration)

External drive information

Calibration

Indications are calibrated on every channel. Indication are shifted on every channel.

Chart scale position is corrected.

• Memory clear

Initialization of set values (Input types, ranges, scales, units, and chart speeds are reset to the set values at the delivery time from the works, and alarm is initialized to no setting)

Clock is initialized to Jan. 1, 1994. Calibration data are initialized.

Hardware check

Printer check, indicator check, DIP switch check, external drive check, version check, and alarm output contact check

■ OPTIONS

Option name	Description
External drive	The following operation can be done by exter-
	nal contact signals.
	Operation type:
	3-chart speed selection, recording stop, & data printing
	No. of contact points:
	3 no-voltage contacts + 1 point (for a special request)
	Contact capacity: 12V DC, 2mA or higher *The depth is increased by 16mm when this
	option is added.

Option name	Description
Communica-	One of RS-232C, RS-422A, and RS-485
tion interface	is to be specified.
lion interiace	Communication contents:
	Transmission of measured values and sta
	tus information.
	Setinng and confirmation of parameters are
	settable by keys.
	* The depth is increased by 16mm when this
	option is added.
Alarm output	No. of output points: 6 points
(6P)	Alarm type: Absolute value alarm, OR output
(-)	* Differential alarm, change ratio alarm,
	standby alarm and AND output can be offered
	on request.
	Setting level: 2 levels/channels
	Contact capacity:
	Mechanical relay: 100V AC, 0.5A, (Resistive
	load)
	Mechanical relay output (Common to "a" contact and "c" contact)
	: 240V AC, 0.2A, (Resistive load)
	MOS relay output: 240V (AC, DC), 50mA
	(Resistive load)
	The depth is increased by 16mm when this option is
	added.
	And the depth in increased by 27mm when mechanical
	relay "a" contact is added.
Extended	Alarm contact outputs of 12 points and 24
alarm output	points together with alarm output (6P)
	· · · · ·
High-speed	Dot-printing cycle About 2.5sec/dot (when the chart speed is more than 12mm/h)
dot-printing	* The dot printing cycle deffers according to the
	chart speed when the chart speed is less than
	2mm/h.
	2
High voltage	Voltage-dividing resistor is built in.
input	Higher than 5VDC, but lower than 60VDC (channel
1	fixed).
Current	A resistor is built in. Lower than 50mA
input	(channel fixed, the resistor is externally
input	mounted).
Burnout	The pointer overshoots the high limit when in
Bulliout	put signals are interrupted.
	(except for voltage -dividing inputs, voltage/cur
	rent inputs)
	Thermocouple input: Channels are fixed.
	Resistance thermometer input:
	All channels are fixed.
Math function	One of addition subtraction multiplication,
	square root, logarithm (common, natural), temperature
	humidity, integration is to be specified.
CE-marking	humidity, integration is to be specified. • Standards
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment)
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment) EN61010-1 +A2
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment) EN61010-1 +A2 • Rated supply voltage
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment) EN61010-1 +A2 • Rated supply voltage 100 to 240 VAC
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment) EN61010-1 +A2 • Rated supply voltage 100 to 240 VAC • Case
CE-marking	humidity, integration is to be specified. • Standards EN5501 1 Group 1 class A EN50082-2 (industrial environment) EN61010-1 +A2 • Rated supply voltage 100 to 240 VAC

■ REFERENCE MEASURING RANGES

		Reference		Indicating	Min. mea-
	Input type	measuring	Scale	resolution	suring
		range			range
		$\pm 7 \text{mV}$	-7 to + 7 mV	1µV	3.2mV
		±14mV	-14 to +14mV	10μV	6.3mV
Ι,	OC voltage	±25mV ±70mV	-25 to +25mV -70 to +10mV	10μV	11.3mV 31.5mV
1	oc vonage	±/0111V ± 5V	-5 to +5V	10μV	2.3V
	 		-150 to +15°C	1 mV	100°C
		±7mV	-150 to +15°C -200 to +300°C	0.1°C 0.1°C	200°C
	K	±14mV ±25mV	-200 to +600°C	0.1°C	400°C
		±70mV	-200 to +1370°C	1°C	800°C
		±25mV	-200 to +350°C	0.1°C	200°C
	Е	±70mV	-200 to +330 C -200 to +900 °C	0.1 C 1°C	500°C
		±25mV	-200 to +450 °C	0.1°C	300°C
	J	±10mV	-200 to +1200°C	1°C	600°C
		±7mV	-150 to +150°C	0.1°C	100°C
	T.	±14mV	-200 to +250°C	0.1°C	200°C
	T	±25mV	-200 to +400°C	0.1°C	300°C
	R	±25mV	0 to +1760°C	1°C	1200°C
	S	±25mV	0 to +1760°C	1°C	1200°C
	В	±14mV	400 to +1820°C	1°C	1200°C
<u>e</u>		±7mV	0 to +200°C	0.1°C	150°C
dn	N	±14mV	0 to +350°C	0.1°C	300°C
8		±25mV	0 to +700°C	0.1°C	400°C
2		±70mV	0 to +1300°C	1°C	900°C
Thermocouple	WWRe5-26	±70mV	0 to +2320°C	1°C	1900°C
Гh	WWRe0-26	±70mV	0 to +2320°C	1°C	1900°C
l '	PR20-40	±7mV	0 to +1880°C	1°C	1500°C
	PR5-20	±14mV	0 to +1880°C	1°C 1°C	1200°C
	Ni-NiMo	±70mV	0 to +1 310°C	_	700°C
	AuFe-Cr	±7mV	0 to 300K	0.1K	180K
	Platinel	±7mV ±14mV	-100 to +150°C -100 to +300°C	0.1°C 0.1°C	100°C 200°C
	Platinei	±25mV	-100 to +500 °C	0.1 °C	400°C
		±23mV ±70mV	-100 to +000 C	1°C	800°C
		±7mV	-150to+150°C	0.1°C	100°C
	U	±14mV	-200 to+250°C	0.1°C	200°C
		±25mV	-200 to+450°C	0.1°C	300°C
		±70mV	-200 to+600°C	1°C	600°C
	L	±25mV	-200 to +450°C	0.1°C	300°C
		±70mV	-200 to +900°C	1°C	600°C
		120Ω	-50 to +50°C	0.1°C	50°C
<u>_</u>		140Ω	-100 to +100°C	0.1°C	100°C
ete	Pt100	160Ω	-140 to +150°C	0.1°C	150°C
Ĕ		220Ω	-200 to +300°C	0.1°C	200°C
1 8		340Ω	-200 to +649°C	0.1°C	400°C
en		120Ω	-50 to +50°C	0.1°C	50°C
t		140Ω	-100 to +100°C	0.1°C	100°C
ce	JPt100	160Ω	-140 to +150°C	0.1°C	150°C
ЭÙ		220Ω	-200 to +300 °C	0.1 °C	200°C
St		-			
Resistance thermometer	Old Pt50	340Ω	-200 to +649°C	0.1°C	400°C
ď		220Ω	-200 to +649°C	0.1°C	300°C
پ	Pt-Co ution) The r	220Ω	4 to 374K	0.1K	200K

The minimum measuring ranges of the temperature scale are reference values. (They vary more or less according to the temperature ranges.) * Caution)

■ STANDARD SCALES

_		337 11			
In	put type	Working reference	Standard scale		
F == - J P =		measuring			
		~range			
	DC	±7mV ±14mV	- 5 to + 5mV, 0 to 5mV -10 to +10mV, 0 to 100mV		
١	oltage/	±25mV	0 to 20mV		
	currenty	±70mV	0 to 50mV		
		± 5 v	1 to 5V, 4 to 20mA, 10 to 50mA		
			(The scale plate is equally divided into 0 to 100 divisions)		
		±7mV	0 to 100°C, 0 to 150°C		
			-50 to +100°C, -50 to +150°C		
		±14mV	-100 to +50°C 0 to 200°C, 0 to 250°C, 0 to 300°C		
	K	±14111V	-50 to +200°C, -100 to +200°C		
		±25mV	0 to 400°C, 0 to 500°C, 0 to 600°C		
		±70mV	0 to 800°C, 0 to 1000°C, 0 to 1200°C		
		±25mV	0 to 200°C, 0 to 300°C		
	E		-50 to +150°C		
		±70mV ±25mV	0 to 500°C, 0 to 600°C, 0 to 800°C 0 to 300°C, 0 to 400°C		
	J	±23mV ±70mV	0 to 600°C, 0 to 800°C, 0 to 1000°C		
	·	, ,	0 to 1200°C		
		±7mV	0 to 100°C, 0 to 150°C		
	Т		-50 to +100°C, -50 to +150°C -100 to +50°C		
	•	±14mV	0 to 200°C, 0 to 250°C		
		.05 **	-50 to +200°C, -100 to +200°C		
	R	±25mV ±25mV	0 to 300°C, 0 to 400°C		
ple	K	±23111V	0 to 1200°C, 0 to 1400°C, 0 to 1600°C, 400 to 1600°C		
ņ	_	±25mV	0 to 1400°C, 0 to 1600°C		
Thermocouple	S		400 to 1600°C 0 to 1200°C, 0 to		
err	В	±14mV	0 to 1600°C, 0 to 1800°C		
Th			400 to 1600°C		
		±7mV	0 to 150°C, 0 to 200°C		
	N	±14mV ±25mV	0 to 300°C 0 to 400°C, 0 to 500°C, 0 to 600°C		
		±10mV	0 to 1000°C, 0 to 1200°C		
	PR20-40	±7mV	0 to 1600°C		
	PR5-20	±14mV	0 to 1200°C, 0 to 1400°C, 0 to 1600°C		
	Ni-NiMo	±70mV	0 to 800°C, 0 to 1000°C o to 1200°C		
		±7mV	0 to 100°C, 0 to 150°C -50 to +100°C, -50 to +150°C		
	Platinel	±14mV	0 to 200°C, 0 to 250°C, 0 to 300°C		
			-100 to +200°C		
		±25mV ±70mV	0 to 400°C, 0 to 500°C, 0 to 600°C 0 to 800°C, 0 to 1000°C,		
		±/0IIIV	0 to 1200°C		
		±7mV	0 to 100°C, 0 to 150°C		
		.14 37	-50 to +100°C, -50 to +150°C,		
	U	±14mV	0 to 200°C, 0 to 250°C -50 to +200°C		
			-100 to +200°C		
		±25mV ±70mV	0 to 300°C, 0 to 400°C 0 to 600°C		
		±70mV ±25mV	0 to 300°C, 0 to 400°C		
	L	±70mV	0 to 600°C, 0 to 800°C		
	-	120Ω	-50 to +50°C, 0 to 50°C		
		140Ω	0 to +100°C, -20 to +80°C -100 to +50°C, -50 to +100°C		
ter	Pt100		50 to 100°C, -40 to +80°C		
me		160Ω	0 to 150°C, -50 to +150°C		
Jou.		220Ω	0 to 200°C, 0 to 250°C, 0 to 300°C -50 to +250°C, -100 to +200°C		
Resistance thermometer		340Ω	0 to 400°C, 0 to 500°C, 0 to 600°C		
e tł		120Ω	-50 to +50°C, 0 to 50°C		
anc		140Ω	0 to 100°C, -20 to +80°C -100 to +50°C, -50 to +100°C		
ista	JPt100	160Ω	50 to 100°C, -40 to +80°C		
ses		220Ω	0 to 150°C, -50 to +150°C 0 to 200°C, 0 to 250°C, 0 to 300°C		
ഥ		2400	-50 to +250°C, -100 to +200°C		
L		340Ω	0 to 400°C, 0 to 500°C, 0 to 600°C		

^{*}Select the combinations of input scales out of the following four kinds in case of the scales by points.

1. Thermocouple, DC voltage type 1: 7mV, 14mV, 25mV, 5V

2. Thermocouple, DC voltage type 2: 14mV, 25mV, 70mV, 5V

3. Resistance thermometer, 5V type 1: 1200, 140 Ω, 160 Ω, 5V

4. Resistance thermometer, 5V type 2: 160 Ω, 220 Ω, 340 Ω, 5V



■ ACCESSORIES


Name of accessories	Q'ty	Remarks
Recording chart	1 pad	Fan-fold type, 20m in total length
Mounting bracket	2 pcs.	Used for panel mounting.
Channel indicating card	1 sheet	Attached to the door for describing the measuring titles of individual channels (The functions of DIP switches are described on the rear panel).
Ribbon cassette	1 pc.	6-color ink ribbon for analogue and digital recording
Auxiliary terminal screw	5 pcs.	Use these input (alarm) terminal screws if they are missing (3.5mm in thread diameter).
Lubricating oil	1 bottle	Contains 10cc.
Instruction manual	1 pad	
Inspection certificate	1 sheet	

■ CONSUMABLES

Article names	Sales unit
Recording chart	15 pads/case
6-color ink ribbon	1 pc/case
cassette	
Lubricating oil	1 bottle
Mounting bracket	2 pcs. (for one unit)


■ TERMINAL BOARD






EXTERNAL DIMENSIONS

Panel Cutout/Minimum instrument mountin Space



:: 211mm (for external drive, alarm output and communication interface)
222mm (for mechanical relay 'a" contact output)



Unit: mm



HOW TO ORDER

1. Model : BH□□□□□□□

2. Power source: 100VAC line or 200VAC line

(To be specified)

*No need to specify the above for CE-marking

(100 to 240VAC free power source)

3. Chart speed : Standard 12.5, 25, 50mm/h

Specified

mm/h

4. Input type and scale:

4. Input type and scale:			
Point No.	Input type	Scale range (incl.deci.point)	Printing unit
		to	

Example

Point No.	Input type	Scale range	Printing unit
1-3	K	0.0 to 400.0	°C

Printing unit is 2 digits. (°C shows 2 digits.)

Shunt resistor for current input:

Built-in or external

5. Scale Plate:

	Scale range	Unit
1.		
2.		
3.		
4.		
5.		
6.		

^{*}Maximum 6 multi scale

Unit: Max. 10 characters (Single scale)
Max.6 characters (Multi scale)

6.Alarm option:

Alarm designation: Standard .Exclusive

- In case exclusive is specified, write exclusive specifications in the right table.
- Parenthesized () settings show the standard settings.
- · Enter alarm set values by keys.
- · Alarm output is up to 2 levels per channel.
- Alarm type: H; High limit absolute value alarm, L; Low limit absolute value alarm, B; Differencial high limit alarm, S; Differencial low limit alarm, U; Change ratio increase limit alarm, D; Change ratio decrease limit alarm These alarms are settable. Fill the option parameters

- with a reference channel when the differential alarm is selected, or fill the option parameter with scanning cycle (1 to 9) when the change ratio alarm is selected. Add W to the alarm type, if a standy alarm is necessary. (Example: WH, WL)
- An alarm output AND connection is possible. Write in the option parameters.

OR output: Alarm output is executed when one of alarm points becomes alarm condition.

AND output: Alarm output is executed when all alarm points become alarm condition.

 Alarm output numbers are freely settable. Example: 24-point alarm outputs are possible on 12-point instrument. (when using extended alarm output 24 points)

alarm output 24 points)							
Points	Level	Alarm type	Output No.	Alarm set value	Para- meters		
	1	(H)	(1)				
1	2	(L)	(1)				
	1	(H)	(2)				
2	2	(L)	(2)				
	1	(H)	(3)				
3	2	(L)	(3)				
	1	(H)	(4)				
4	2	(L)	(4)				
	1	(H)	(5)				
5	2	(L)	(5)				
6	1	(H)	(6)				
	2	(L)	(6)				
	1	(H)	(7)				
7	2	(L)	(7)				
	1	(H)	(8)				
8	2	(L)	(8)				
	1	(H)	(9)				
9	2	(L)	(9)				
	1	(H)	(10)				
10	2	(L)	(10)				
	1	(H)	(11)				
11	2	(L)	(11)				
1.0	1	(H)	(12)				
12	2	(L)	(12)				
	1	(H)	(13)				
13	2	(L)	(13)				
14	1	(H)	(14)				
14	2	(L)	(14)				
1.5	1	(H)	(15)				
15	2	(L)	(15)				
	1	(H)	(16)				
16	2	(L)	(16)				
	1	(H)	(17)				
17	2	(L)	(17)		-		
	1	(H)	(18)				
18	2	(L)	(18)				
	1	(H)	(19)				
19	2	(L)	(19)				
2.0	1	(H)	(20)				
20	2	(L)	(20)				
	1	(H)	(21)				
21	2	(L)	(21)				
	1	(H)	(22)				
22	2	(L)	(22)				
23	1	(H)	(23)				
	2	(L)	(23)				
2.4	1	(H)	(24)				
24	2	(L)	(24)				

Specifications subject to change without notice. Original 2001.5

CHINO CORPORATION

32-8, KUMANO-CHO, ITABASHI-KU, TOKYO 173-8632 PHONE: +81-3-3956-2171

FAX: +81-3-3956-0915 E-mail: inter@chino.co.jp Webside: http://www.chino.co.jp